

N
↑

NO SCALE

1. MON. 23 JULY '90 OLA RLS 0537, P. MAHER &
FOUND NO METAL SOUNDING; ROAD ALIGNMENT
& ELEVATION PRECLUDES DIG. AIR PHOTO ALIGNMENT
THROWS POSITION IN DITCH OR ON SOUTH SPOIL BANK,
& ELEVATION DUE TO DITCH SPOILS ON ROADWAY
WOULD CAUSE A MINIMUM 6' CUT. DIG NOT
ADVISABLE; WILL NOT DIG.

DITCH
←

CR 5005
CHIP & SEAL

NORTH 1/4 COR. SEC. 16

NO MONUMENT

J-11