
JACKSON TOWNSHIP

T 33 N, R 3 W J17



COMMENTS: IRON PIPE 40'S OF CORNER AND 6'N OF EOP OF SR 8

CORNER LOCATION IN THE SECTION USED AS A REFERENCE IN 1989 WAS PROBABLY DESTROYED BY INSTALLATION OF GUARD RAIL. UNABLE TO RESET: NO + IN SE WING WALL; NOT KNOWN WHICH PWP TO THE S OR WHICH MAPLE TO THE E ARE THE CORRECT REFERENCES TO THE IRON PIPE. STATE HIGHWAY DEPARTMENT HAS NO INFORMATION AFTER 1989.