

N
↑

NO SCALE

1. TUES 19 JUNE '90 DLA RLS 0537, P. MAYER ϕ .
WHEELED DIST. = 5227' FOR THE MILE. @ 2614 PAINTED SOUTH BERM. DITCH ALONG SOUTH EDGE OF ROAD FORCES ROADWAY NORTH SO THAT SOUTH BERM ALIGNS WITH CORNERS $\frac{1}{4}$ MILE EAST & WEST.
2. WED. 20 JUNE '90 DUG 18' X 20' X 4' DEEP HOLE ALONG BERM & SOUTH EDGE OF GRAVEL ROAD. FOUND NO POST, NO PIT, NO STONE; MONUMENT PROBABLY DESTROYED DURING DITCH CONSTRUCTION; DITCH & ROADWAY SHARE R/W.
3. THUR 21 JUNE '90 SET STEEL FENCE POSTS @ 20' APART NEAR SE & SW COR. OF HOLE ALONG DITCH BANK TOP.

CR300N
GRAVEL



NORTH $\frac{1}{4}$ COR. SEC. 2
 (ACTUALLY S. $\frac{1}{4}$ COR. SEC. 35 T34N)
 - TIFIN SET NO CLOSING $\frac{1}{4}$ COR.

NO MONUMENT

A-19c