

N  
↑  
NO SCALE

1. FRI 13 JULY '90 01A RLS 0537, P. MAYER Q.  
FOUND NO METAL SOUNDING @ FIELD DIVISION  
TO NORTH + ODOMETER 0.5 MILE. DIG NOT  
ADVISABLE BECAUSE DRAINAGE CONSTRUCTION  
& OLD SPILLS IN ROADWAY APPEAR TO HAVE  
DESTROYED POSITION &/OR WOULD NECESSITATE  
EXCESSIVE ≈ 5' + CUT IN ROADWAY. &.  
DO NOT ADVISE DIG

OLD FIELD  
DIVISION

REFER TO 1951  
AIR PHOTO

CR 7005  
GRAVEL

DITCH

NORTH 1/4 COR. SEC. 25

NO MONUMENT

R-23